

GREG BELL Lieutenant Governor

# State of Utah

#### DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection:					
OGM	Steve Demczak				

## **Inspection Report**

Last Inspection:	Monday, August 10, 2009
End Date/Time:	8/10/2010 2:00:00 PM
Start Date/Time:	8/10/2010 9:00:00 AM
Inspection Date:	Tuesday, August 10, 2010
Inspection Type:	COMPLETE
Permit Number:	C0070021

Inspector: Steve Demczak,

Weather: Sunny, 70's

InspectionID Report Number: 2451

Accepted by: jhelfric

8/12/2010

Permitee: **BLAZON** 

Operator:

Site: BLAZON #1 MINE

Address: ,

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreag	es
----------------	----

Total Permitted	7.00
Total Disturbed	7.00
Phase I	
Phase II	
Phase III	

Federal Underground
State Surface
County Loadout
Fee Processing
Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Date



Steve Demczak,

Inspector ID Number: 39

Permit Number: C0070021 Inspection Type: COMPLETE

Inspection Date: Tuesday, August 10, 2010

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	•		<b>~</b>	
2.	Signs and Markers	<b>~</b>		<b>✓</b>	
3.	Topsoil	<b>~</b>		<b>✓</b>	
4.a	Hydrologic Balance: Diversions	<b>V</b>		<b>~</b>	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		<b>V</b>		
4.c	Hydrologic Balance: Other Sediment Control Measures	<b>V</b>		<b>✓</b>	
4.d	Hydrologic Balance: Water Monitoring		<b>V</b>		
4.e	Hydrologic Balance: Effluent Limitations		<b>✓</b>		
5.	Explosives		<b>✓</b>		
6.	Disposal of Excess Spoil, Fills, Benches		<b>V</b>		
7.	Coal Mine Waste, Refuse Piles, Impoundments		<b>✓</b>		
8.	Noncoal Waste	<b>✓</b>		<b>~</b>	
9.	Protection of Fish, Wildlife and Related Environmental Issues	<b>~</b>		<b>~</b>	
10.	Slides and Other Damage	<b>~</b>		<b>✓</b>	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	•		~	
13.	Revegetation	✓		<b>Y</b>	
14.	Subsidence Control		<b>✓</b>		
15.	Cessation of Operations		<b>V</b>		
16.	Roads: Construction, Maintenance, Surfacing		<b>V</b>		
	Roads: Drainage Controls		<b>✓</b>		
17.	Other Transportation Facilities		<b>V</b>		
18.	Support Facilities, Utility Installations		<b>✓</b>		
19.	AVS Check		<b>V</b>		
20.	Air Quality Permit		<b>V</b>		
21.	Bonding and Insurance		<b>V</b>		
22.	Other		<b>V</b>		

Permit Number: C0070021 Inspection Type: COMPLETE

Inspection Date: Tuesday, August 10, 2010

Page 3 of 3

## 1. Permits, Change, Transfer, Renewal, Sale

This site was first reclaimed by the permittee in the late 1980s and later by the Division in the 1990s after the permittee left the country.

## 2. Signs and Markers

No identification was at the main gate.

#### 3. Topsoil

All topsoil was used in the reclamation.

#### 4.a Hydrologic Balance: Diversions

The diversion were functioning as designed. The Muddy creek diversion pasting through the site had flowing water.

## 4.c Hydrologic Balance: Other Sediment Control Measures

The site was pocked for sediment control.

#### 8. Noncoal Waste

The site was clear of non-coal waste materials.

### 9. Protection of Fish, Wildlife and Related Environmental Issues

Wildlife have been grazing in the reclaimed area.

#### 10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

### 12. Backfilling And Grading

The mine site was completely backfilled and graded.

### 13. Revegetation

The site has been revegetated with many different types of plant life. Thistle is starting to come up along the old road and near the stream.